ECS/EMD Configuration Change Request					Page 1 of Page(s)		
1. Originator	2. Log Date:	3. CCR #:	4	4. Rev:	5. Tel:	6. Rm #:	7. Org.
Ron Parham	09/22/04	04-0488		_	0713	3108D	HW COTS
8. CCR Title: TCP Driver Fix for IBM Firewall							
9. Originator Signature/Date			10. Cla	10. Class 11. Type: 12. Need Date: 9/23/0		: 9/23/04	
Ronald A. Parham /s/ 9/17/04			II		CCR		
13. CCR Sponsor Signature/Date			14. Category o		15. Priority: (If "Emergency" fill in Block 27).		
Pamela Johnson /s/ 9/21/04				PRO Till in Block 27). Routine			
16. Documentation/Drawings Impacted (Review and submit checklist): N/A 1				dule 18. CI(s) Affected:N/A			
•			to Customer: 21. Estimated Cost:				
N/A 9/29/04				None Officer Foots			
22. Source Reference: ⊠NCR (attach) □Action Item □Tech Ref. □GSFC □Other: ECSed40527							
23. Problem: (use additional Sheets if necessary) Host g0fwi10 halted on 05/18/2004 at 19:44 which interrupted MODAPS connectivity to PDR Server. IBM technical support was contacted 05/19/2004 (reference code 32RS387) for assistance. Host required power cycling before console prompt was returned. Executed a series of hardware diagnostics which returned error free. Error appears software related.							
24. Proposed Solution: (use additional sheets if necessary) IBM recommended installing patch fix "bos.net.tcp.server.5.1.0.51". The patch fix would be installed on the GES DAAC firewall, g0fwi10.							
25. Alternate Solution: (use additional sheets if necessary) None							
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Possibility of the reoccurrence of interrupted MODAPS flows.							
27. Justification for Emergency (If Block 15 is "Emergency"): None							
28. Site(s) Affected: DEDF DVC VATC DEDC SFC LaRC NSIDC SMC AK JPL DEOC DIDG Test Cell Other]JPL	
29. Board Comments:				30. V	Vork Assigned T	o: 31. CCR (Closed Date:
32. SCDV CCB Chair (Sign		Disposition: Ar	oproved	App/Co	om. Disapproved	Withdraw Fw	d/ESDIS ERB
Byron V. Peters /s/ 9	9/21/04	Fv	vd/ECS				
33. EDF CCB Chair (Sign/D	Pate):	Disposition : Ap	Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB				
34. ECS CCB Chair (Sign/D	Pate): Di	sposition: App		App/Cor	n. Disapproved	Withdraw Fw	d/ESDIS ERB
· · · · · · · · · · · · · · · ·			Fwd/ESDIS				

CM01JA00 Revised 10/2/03 ECS/EDF/SCDV

ADDITIONAL SHEET

CCR #: 04-0488 Rev: — Originator: Ron Parham

Telephone: 301 925 0713 **Office:** HW COTS

Title of Change: TCP Driver Fix for IBM Firewall

Installation Instructions for IBM TCP Driver Fix

1.0 Purpose

The purpose of this document is to define the steps required to install the TCP driver fix in the IBM Model 7028-6E4 server (a.k.a. Portus Firewall).

2.0 Scope

smit

This document can be used by engineering, installation, and maintenance personnel to install the IBM TCP driver fix the Portus Firewall. It does not replace training provided by IBM.

3.0 Related Documentation

3.1 IBM Documentation

The following IBM information was used to develop the step-by-step procedures:

- 1. On-line documentation from IBM's Web Site at http://www.ibm.com
- 2. Installation Guide for Server pSeries 630 Model 6E4 e-server

Use SMIT to perform the software install:

4.0 Fileset Update Procedures

Download from the IBM AIX website the updated filesets for the base operating system commands supporting top drivers. Type the following commands: #mkdir /tmp/tcpfix 8 #cd /tmp/tcpfix 8 #ftp://www7b.boulder.ibm.com/ 8 Connected to www7b.boulder.ibm.com. 220-*** 220-* 220-* IBM's internal systems must be used only for conducting IBM's business 220-* or for purposes authorized by IBM management. 220-* 220-* Use is subject to audit at any time by IBM management. 220-* 220-220 www7b.boulder.ibm.com FTP server (Version wu-2.6.2(4) Custom Thu Feb 12 14:27:47 MST 2004) ready. User (www7b.boulder.ibm.com:(none)): anonymous 331 Guest login ok, send your complete e-mail address as password. Password: 230-Please read the file README 230- it was last modified on Thu Aug 9 08:15:27 2001 - 697 days ago 230 Guest login ok, access restrictions apply. #ftp>cd aix/fixes/byCompID/5765E6100/bos.net/ 8 #ftp>bin 8 #ftp>get bos.net.tcp.server.5.1.0.51.bff 8 #ftp>get bos.net.tcp.server.5.1.0.51.info 8 #ftp>bye 8 Verify the download into /tmp/tapefix and execute an AIX "sum" command: 2. # sum bos.net.tcp.server.5.1.0.51.bff 8 40039 5875 bos.net.tcp.server.5.1.0.51.bff # sum bos.net.tcp.server.5.1.0.51.info 8 04701 1 bos.net.tcp.server.5.1.0.51.info 3. Build the .toc file required by the installation program # inutoc . 8

The first menu heading will read:
Software Installation and Maintenance
Select the heading:
Install and Update Software
Select the heading:
Update from Latest Available Software

A popup menu is displayed. At the "Input device / directory for software," type in:

/tmp/tcpfix

Click the OK button

A new popup window will appear. Make the following selections for the appropriate boxes:

Software to install = click on the "list" button, a "Multi-Select List" window will popup. From this window select:

bos All bos_all_filesets bos.net All bos.net all filesets

Then click the OK button which will return to the previous window. Continue with the following selections:

Preview only ? = no
Commit software updates? = yes
Save replaced files ? = yes
Automatically install required software? = no
Extend file systems if needed? = no
Overwrite same or newer versions = no
Verify install and check file sizes = no
Include corresponding Language filesets ? = yes
Detailed output ? = yes

Process multiple volumes ? = no

Click on OK to start the install process. Upon a successful completion the running man will raise his hands.

CM01AJA00 Revised 10/2/03 ECS/EMD